

# T and R Group

## Roads and Pavements May 1st 2010

### Swanston Fields



Gutter clogged with leaves



Builders did not replace the sets



Weeds in kerbs



### Hardwick Road



Typical kerb condition.



Deep mud hole at the top of Muddy Lane

# T and R Group

## Roads and Pavements May 1st 2010

### Eastfield Lane



Drainage work needed



Why leave the middle bit?



Lots of potholes!



Road surface damage in the region of the new buildings



Entrance from the High Street.

White line work needed




Typical small pothole



# T and R Group

## Roads and Pavements May 1st 2010

### Manor Road



Lower part of  
Manor Road  
Estate



Upper part of  
Manor Road  
Estate

For  
Comparison



### Upper High Street



You can put your foot in it!

# T and R Group

## Roads and Pavements May 1st 2010

### High Street



Original hole was repaired badly



Debris from the potholes



Now look at it!

This used to be a bollard.

